

APPLE COMPUTER INC.
820-0650-B © 1992
630-

10µf
16V

10µf
16V

10µf
16V

10µf
16V

100µf
6.3V

47µf
16V

Mac LC III (Performa 450)

- 5 x 10µf 16V
- 5 x 47µf 16V
- 1 x 100µf 6.3V

47µf
16V

10µf
16V

47µf
16V

47µf
16V

47µf
16V

Original orientation incorrect.
Replacement capacitor should be
installed in the opposite polarity
to the screenprinting.

25336H7EN6-

SINGAPORE REV D

ZH2

Version 1.01